Errata

Volume 2, Number 1

Page 30, line 19
  AM2901   should be   AM2910

Page 31, line 38
  LDB.F   should be   LDB.B

Page 32, line 7
  LDB.F   should be   LDB.B

Volume 2, Number 2

Page 26, line 21
  [ars1   [ars2]]   should be   [arg1   [arg2]]

Page 42, line 1
  Vehicle Guidance   should be   a subheading below *Subsystems*

Page 46, line 19
  KEYPAD-IDENTIFICATION   should be   KEYPAD-IDENTIFICATION !

Page 47, line 29
  The following definition was omitted:
  : DISPLAY-LINE   BLANK-DISPLAY
          28 0 DO   SET-POSITION
                      GET-CHARACTER
                      SEND-CHARACTER
              LOOP   ;

Page 48, line 27
  2 / +   should be   4 / +

Page 53 and 54
  Figure 6 and Figure 7 were reversed.